




Business Jet Center
8611 Lemmon Avenue
Dallas, Texas 75209



Hangar conditions at project start




General cleaning / Initial floor preparation



Business Jet Center
8611 Lemmon Avenue
Dallas, Texas 75209



Setting up / Shot blasting started



Floor shot blasted / Cracks filled / Imperfections repaired



Business Jet Center
8611 Lemmon Avenue
Dallas, Texas 75209



Floor shot blasted / Imperfections repaired / E31-1202-64 epoxy primer applied



Business Jet Center
8611 Lemmon Avenue
Dallas, Texas 75209



E31-1202 100% solids epoxy being applied (using spikes, squeegees, and then “back-rolled”)
/ 3M quartz aggregate mixed (a special blend of white / gray / and black) then broadcast



Business Jet Center
8611 Lemmon Avenue
Dallas, Texas 75209




E31-1202 applied / Quartz aggregate being broadcast “to excess” / Quartz aggregate was a special color blend (broadcast twice) / Almost 35,000 pounds of aggregate and over 1200 gallons of coating were applied (with the finished system in excess of 1/8 inch thick).

A clear aliphatic urethane was applied as the finish coat.



Business Jet Center
8611 Lemmon Avenue
Dallas, Texas 75209



Finished floor