

Christian Brothers Automotive



4121 State Highway 121
Carrollton, Texas 75006

General Contractor:
Halstead Contractors, LLC
5455 Troy Highway
Montgomery, Alabama 36116

CHRISTIAN BROTHERS AUTOMOTIVE CARROLLTON, TEXAS Automotive Shop Floor



Condition of Floor Drains at Project Start


Christian Brothers Automotive




4121 State Highway 121
Carrollton, Texas 75006

General Contractor:
Halstead Contractors, LLC
5455 Troy Highway
Montgomery, Alabama 36116


CHRISTIAN BROTHERS AUTOMOTIVE CARROLLTON, TEXAS Automotive Shop Floor



Floor Primed with E31-1203 Epoxy Primer after Shot Blasting



Holes/Cracks Filled with E31-1204 Crack Filler



Drains Initially Filled With E31-1202 100% Solids Epoxy



Drains Filled / Repaired / Diamond Ground Flush to Floor

Christian Brothers Automotive



4121 State Highway 121
Carrollton, Texas 75006

General Contractor:
Halstead Contractors, LLC
5455 Troy Highway
Montgomery, Alabama 36116

CHRISTIAN BROTHERS AUTOMOTIVE CARROLLTON, TEXAS Automotive Shop Floor

Were there any problems with this project? YES! In the course of filling/repairing the spalled, broken out drains, we accidentally poured epoxy down in the drains (not realizing there were vent holes in the drains themselves). Again, in the course of filling the broken out areas around the drains and not knowing of the vent holes beneath the surface, we accidentally poured epoxy and subsequently clogged the drains. We had no alternative but to saw cut out and replace the drain elbows.



These photographs display the cutting, breaking-out process, and the placing of new drains.

Christian Brothers Automotive



4121 State Highway 121
Carrollton, Texas 75006

General Contractor:
Halstead Contractors, LLC
5455 Troy Highway
Montgomery, Alabama 36116

CHRISTIAN BROTHERS AUTOMOTIVE CARROLLTON, TEXAS Automotive Shop Floor



U31-1201 High Performance Urethane Topcoats Applied / Green Pads Installed