

Gulfstream®

A GENERAL DYNAMICS COMPANY

HANGAR FLOOR REFURBISHMENTS A CASE HISTORY

Hangars A, B, D & E
Love Field, Dallas, Texas


The attached photographs show hangar floor refurbishments, during the 2005 Holiday period. Because **Gulfstream / Dallas** is a very busy service facility, with a high level of activity (Hangar D services over 1200 aircraft per year alone), we had a limited amount of time for each hangar [approximately five (5) days per hangar floor].



GULFSTREAM

SERVICE HANGARS

Gulfstream







Gulfstream®





A GENERAL DYNAMICS COMPANY

Considered by most as the ultimate choice in business aircraft, Gulfstream is constantly building, refurbishing, and generally improving/upgrading facilities to uphold this high standard.

HANGAR FLOOR COATING SPECIFICATIONS

1. Power sand/diamond grind entire floor (100%). Prepare surface for coating/profile hangar floor/detergent clean.
2. Crack fill/repair floor imperfections (E31-1204).
3. Apply 1st color coat (E31-1202) with non-skid quartz aggregate.
4. Apply 2nd color topcoat (U31-1201).
5. Clean Up.

Hangar D



Hangar D

